

Oil Field Environmental Incident Summary

Incident: 20160711093601 **Date/Time of Notice:** 07/11/2016 09:36

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: PARSHALL SECTION 30 NWNE CENTRAL FACILITY

Field Name: PARSHALL

Well File #:

Date Incident: 7/10/2016 **Time Incident:** 10:00 **Facility ID Number:** 229261-01

County: MOUNTRAIL **Twp:** 152 **Rng:** 90 **Sec:** 30 **Qtr:** NW NE

Location Description:

Submitted By: Matt Richards

Received By:

Contact Person: Matt Richards
600 17TH ST STE 1000N
DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	2	barrels

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received: 8/31/2016

Clean Up Concluded: 7/11/2016

Risk Evaluation:

None

Areal Extent:

Potential Environmental Impacts:

None

Action Taken or Planned:

Free standing fluid was sucked up and the contaminated soil was removed from location

Wastes Disposal Location: Newalta

Agencies Involved:

Updates

Date: 7/11/2016 ***Status:*** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, the release remained within location boundaries. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.